DCDIDCB

TE07

FEB 1 9 1991

X-R-I Testing, Inc. Division of X-Ray Industries ATTN: Leonard H. Schlipp Radiation Safety Officer 120 James Street Holland, MI 49424 License No. 21-05472-01 Docket No. 030-04837

Gentlemen:

This refers to the special safety inspection conducted by Mr. B. A. Parker of this office on January 17, 1991, of activities authorized by NRC Byproduct Material License No. 21-05472-01, and to the discussion of our findings with you and Mr. James Broadbent at the conclusion of the inspection.

The inspection was initiated in response to allegations which were received by the NRC Region III office on November 20, 1990. The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appear to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

The response directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

John A. Grobe, Chief Nuclear Materials Safety Branch

Enclosures: 1. Notice of Violation 2. Inspection Report No. 030-04837/91001(DRSS)

cc w/enclosures: DCD/DCB(RIDS) Kirk Thams, XRI Corporate Headquarters

9102270364 910219 REG3 LIC30 21-05472-01 PD bcc w/enclosures: D. Funk, RIII PDR Caniàno