

ENCLOSURE

NOTICE OF VIOLATION

Mennonite General Hospital  
Aibonito, Puerto Rico

Docket No. 030-31223  
License No. 52-25058-01

During an NRC inspection conducted on February 13, 1991, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1990), the violation is listed below:

Condition 13 of NRC License No. 52-25058-01 requires that licensed radioactive material be possessed and used in accordance with the statements, representations and procedures described in the license application dated June 15, 1989, and in the documents submitted in support of that application.

Item 10.2.1(b) of the license application requires that the licensee perform a formal annual review of the radiation safety program, including ALARA (as low as reasonably achievable) considerations.

Contrary to the above, a formal review of the radiation safety program was not performed for 1989 or 1990.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, Mennonite General Hospital is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with a copy to the Regional Administrator, Region 11, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include [for each violation]: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, an order may be issued to show cause why the license should not be

9103250384 XA

ZPP


Mennonite General Hospital  
Aibonito, Puerto Rico

2

Docket No. 030-31223  
License No. 52-25058-01

modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

FOR THE NUCLEAR REGULATORY COMMISSION



William E. Cline, Chief  
Nuclear Materials Safety and  
Safeguards Branch  
Division of Radiation Safety  
and Safeguards

Dated at Atlanta, Georgia  
this 6 day of March 1991