

WATERGATE RADIOLOGY, P.C.

2524 VIRGINIA AVENUE, N.W.

WASHINGTON, D.C. 20037

PAUL H. PEVSNER, M.D.
DOROTHY F. COONEY, M.D.

(202) 342-9406

November 2, 1982

Thomas T. Martin, Director
Division of Engineering of Technical Programs
United States Nuclear Regulatory Commission
Region One
631 Park Avenue
King of Prussia, PA 19406

Dear Mr. Martin,

This is in response to your letter of October 5, 1982 regarding inspection Number 82-01 made by Mrs. T. H. Darden on August 16, 1982 regarding activities authorized by NRC, License Number 08-19896-01.

The two deficiencies were the absence of ring badges and failure to use syringe shields during injection of radionuclide.


The ring shields were ordered immediately and have been in use since September of 1982, and we now routinely use one of our two syringe shields during injection of radionuclide materials.

Both the ring badges and the syringe shields are available for inspection in our offices.

I have instructed our technologist in the applicable provisions of the commission's regulations and licenses and they are posted in the room and available for perusal.

If you have any further questions, please feel free to contact me directly.

Yours truly,



Paul H. Pevsner, M.D.

8211290676 821122
NMS LIC30
08-19896-01 PDR