



Carolina Power & Light Company

H. B. ROBINSON STEAM ELECTRIC PLANT  
POST OFFICE BOX 790  
HARTSVILLE, SOUTH CAROLINA 29550

NOV 17 1982

INRC REGION  
ATLANTA, GA  
22 NOV 24 4 08 50

Robinson File No: 13510C

Serial: RSEP/82-1821

Mr. James P. O'Reilly  
Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2  
DOCKET NO. 50-261  
LICENSE NO. DPR-23  
LICENSEE EVENT UPDATE REPORT 81-001, REVISION 1

Dear Mr. O'Reilly:

In accordance with Section 6.9.2 of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit No. 2, the enclosed Licensee Event Update Report is submitted. The original report, dated January 23, 1981, described an event in which the turbine runback and automatic rod withdrawal block protection systems were defeated concurrent with power range channel N41 being out of service. This revision contains a complete description of the original event plus new information resulting from analysis performed by the fuel supplier. New information is indicated by a vertical bar in the right hand margin. This report, therefore, supersedes and should replace all copies of the original report.

Very truly yours,

R. B. Starkey, Jr.  
General Manager  
H. B. Robinson SEG Plant

HTC/bss

Enclosure

cc: R. C. DeYoung (40)  
R. A. Hartfield (3)

OFFICIAL COPY  
I E 22