



January 29, 1991

2CAN019110

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Mail Station P1-137  
Washington, DC 20555

SUBJECT: Arkansas Nuclear One - Unit 2  
Docket No. 50-368  
License No. NPF-6  
Annual Report of the Steam Generator  
Tube Inservice Inspections - 1990


Gentlemen:

The Arkansas Nuclear One, Unit 2 (ANO-2) Technical Specifications 4.4.5.5 and 6.9.1.5.b requires the complete results of all ANO-2 steam generator tube inservice inspections (ISI) performed during the report period be submitted on an annual basis. The purpose of this letter is to provide the required report for 1990.

During 1990 Entergy Operations did not perform ISIs on the ANO-2 steam generators tubes. The last ANO-2 steam generator tube ISI was performed during the last refueling outage (2R7) in September and October of 1989. The results of the inspections were reported in letter 2CAN089006 (dated August 2, 1990). The next steam generator tube ISI is scheduled for the upcoming refueling outage (2R8).

This submittal completes the reporting requirements of ANO-2 Technical Specifications 4.4.5.5 and 6.9.1.5.b. Should you have any questions regarding this issue, please contact me.

Very truly yours,

  
James J. Fisicaro  
Manager, Licensing

JJF/RWC/sgw

AOA7  
1/0

cc: Mr. Robert Martin  
U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX 76011

NRC Senior Resident Inspector  
Arkansas Nuclear One - ANO-1 & 2  
Number 1, Nuclear Plant Road  
Russellville, AR 72801

Mr. Thomas W. Alexion  
NRR Project Manager, Region IV/ANO-1  
U. S. Nuclear Regulatory Commission  
NRR Mail Stop 11-B-19  
One White Flint North  
11555 Rockville Pike  
Rockville, Maryland 20852

Ms. Sheri Peterson  
NRR Project Manager, Region IV/ANO-2  
U. S. Nuclear Regulatory Commission  
NRR Mail Stop 11-B-19  
One White Flint North  
11555 Rockville Pike  
Rockville, Maryland 20852