## YANKEE ATOMIC ELECTRIC COMPANY



2.

Rowe, Massachusetts 01367

November 8, 1982

Mr. R. C. Haynes, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region I 631 Park Avenue King of Prussia, Pennsylvania 19406

Subject: Licensee Event Report 50-29/82-33-03L Refueling Nuclear Changes Inadvertently De-energized

Dear Mr. Haynes:

In accordance with Technical Specifications, Section 6.9.4.b the attached Licensee Event Report is hereby submitted.

Very truly yours,

Mentert a, antis

Herbert A. Autio Plant Superintendent

ELM/amt

Enclosures:

- cc: [30] Director, Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555
  - [3] Director, Officer of Management Information & Program Control U.S. Nuclear Regulatory Commission Washington, D.C. 20555
  - [14] NSARC Chairman
  - [1] Manager of Operational Quality Assurance (YAEC)
  - [1] Institute of Nuclear Power Operations (INPO)

-E72