LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 I L D R S 3 2 0 0 - 0 0 0 0 - 0 0
CON'T 0 1 SOURCE L 6 0 5 0 0 0 2 4 9 7 1 0 2 1 8 2 8 1 1 1 7 8 2 9
During review of monthly Fire Protection Surveillances DFPP 4114-2, Reactor Building
Monthly Fire Equipment Inspection and DFPP 4114-3, Turbine Building Monthly Fire
0 4 Equipment Inspection, it was discovered that the surveillances were partially finished
and exceeded the requirements of being completed within 31 days (including the 25 per-
0 6 cent buffer limit). Safety significance was minimal since the completion of the sur-
0 7 [veillance revealed no problems. There was no effect on the public health or safety.
Previous occurrence reported by R.O. 81-15 on Docket 50-237.
SYSTEM CODE SUBCODE SU
LER/RO EVENT YEAR REPORT NO. 17 REPORT NUMBER REPORT NO. 18 2
ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER SUPPLIER MANUFACTURER SUPPLIER SUPPLIER SUPPLIER MANUFACTURER Z 9 9 9 9 9 26
The cause of the incompleted surveillances was an inadvertent oversight by the opera-
[1] ting shifts. Corrective actions were taken by reviewing the event during operator
112 training class and implementing better administrative procedures via computer surveil-
1 ance checklist. Surveillance will continue to be performed as required.
FACILITY STATUS TO ST
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 1 6 Z 33 Z 34 N/A N/A LOCATION OF RELEASE 36
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 1 7 0 0 0 37 Z 38 N/A
PERSONNEL INJURIES NUMBER DESCRIPTION 41
1 3 0 0 0 0 40 N/A
LOSS OF OR DAMAGE TO FACILITY 43 1 9 Z 42 N/A 8211290766 821117
PDR ADDCK 05000249
2 0 N 44 N/A
NAME OF PREPARER David Tang Wee PHONE: 815-942-2920, X-422 3