Duquesne Light Company

Beaver Valley Power Station P.O. Box 4 Shippingport, PA 15077-0004

JOHN D. SIEBER Senior Vice President and Chief Nuclear Officer Nuclear Power Division February 9, 1994

(412) 393-5255 Fax (412) 643-8069

U. S. Nuclear Regulatory Commission

Attn: Document Control Desk Washington, DC 20555

Subject: Beaver Valley Power Station, Unit No. 1 and No. 2

BV-1 Docket No. 50-334, License No. DPR-66 BV-2 Docket No. 50-412, License No. NPF-73

Annual Report of All Challenges to the Pressurizer Power

Operated Relief Valves or Safety Valves

This report is submitted in accordance with the Beaver Valley Power Station Unit Nos. 1 and 2 Technical Specification 6.9.1.5.b.

Unit 1:

There was one challenge to the pressurizer power operated relief valves (PORVs) at Unit 1 during the period of January 1, 1993, to December 31, 1993.

Date:

November 7, 1993

Plant Conditions:

Mode 4, Reactor Coolant System (RCS) pressure was 385 psig, Overpressure Protection System (OPPS) was not in service. A cooldown to Mode 5 was in progress.

Summary:

Pressurizer Power Operated Relief Valve, PCV-RC-455C, momentarily opened as OPPS was placed into service, reducing RCS pressure by 6 psig. OPPS was placed into service while RCS pressure was in the "trip-reset" region for comparator operations for the PORV.

There were no challenges to the pressurizer safety valves during the period.

Unit 2:

There were no challenges to the pressurizer safety or power operated relief valves at Unit 2 during the period of January 1, 1993, to December 31, 1993.

Sincerely,

9402180001 940209 PDR ADDCK 05000334 PDR

J. D. Sieber

cc: Mr. L. W. Rossbach, Sr. Resident Inspector Mr. T. T. Martin, NRC Region I Administrator

Mr. G. E. Edison, Project Manager

ELECTRIC UTILITY OF THE YEAR

IE 47

as info_ DUQUESNE LIGHT COMPANY Nuclear Power Division Nuclear Operations Unit January 28, 1994 ND3MOA:0215 Challenges to Safety and Power Operated Relief Valves G. S. Sovick: In accordance with Technical Specification 6.9.1.5.b, Duquesne Light is required to report all challenges to the Pressurizer Safety and Power Operated Relief valves (PORV) for Units 1 and 2. The attached is a summary of all challenges from January 1, 1993 to December 31, 1993. Supervisor Reactor Engineering JGT/ke Attachment N. R. Tonet CC: J. G. Treese F. J. Lipchick Central File

Attachment January 28, 1994 ND3MOA:0215

Challenges to Safety and Power Operated Relief Valves

Unit 1:

There was one challenge to the Pressurizer Safety and Power Operated Relief Valves (PORV) at Unit 1 during the period of January 1, 1993 to December 31, 1993.

Date November 7, 1993

Plant Conditions: Mode 4, RCS pressure was 385 psig, Overpressure

Protection System (OPPS) was not in service. A cooldown

to Mode 5 was in progress.

Summary Pressurizer Power Operated Relief Valve, PCV-RC-455C,

momentarily opened while placing OPPS in service, reducing RCS pressure by 6 psig. OPPS was placed in service while RCS pressure was in the "trip-reset" region for

comparator operations for the PORV.

Unit 2:

There were no challenges to the Pressurizer Safety and Power Operated Relief Valves (PORV) at Unit 2 during the period of January 1, 1993 to December 31, 1993.

Prepared by	5 gar	J. G. Treese
Reviewed by	23 grie	G. F. Zupsic
Approved by _	Articlel.	L. R. Freeland