

RECEIVED
NRC

rm
Southern California Edison Company

P. O. BOX 800
2244 WALNUT GROVE AVENUE
ROSEMEAD, CALIFORNIA 91770

1982 OCT 25 PM 12:20
REGIONAL

SCE

TELEPHONE
(213) 972-1695

J. M. CURRAN
MANAGER, QUALITY ASSURANCE

October 22, 1982

Mr. R. H. Engelken, Regional Administrator
U. S. Nuclear Regulatory Commission
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94506

Dear Mr. Engelken:

SUBJECT: Docket No. 50-362
San Onofre Nuclear Generating Station, Unit 3

This letter confirms verbal notification on October 21, 1982 of a condition discovered in construction which is considered potentially reportable in accordance with 10CFR50.55(e).

This condition involves the governor output voltage erratic behavior causing momentary speed changes of the diesel generator, 3G002. The unit is manufactured by Stewart-Stevenson, Houston, Texas.

We are performing an evaluation of this condition and will submit an appropriate report in accordance with 10CFR50.55(e) (3) if the condition is determined to be reportable. If you have any questions or required additional information, please let me know.

The condition is under investigation on Unit 2.

Very truly yours,

J. M. Curran

8212060012 821022
PDR ADOCK 05000362
S PDR

cc: A. E. Chaffee (NRC, San Onofre Units 2 & 3)
Dr. L. T. Papay

IE27

82-371