STATE OF RHODE ISLAND AND PROVIDENCE PLANTATIONS

RHODE ISLAND ATOMIC ENERGY COMMISSION

RHODE ISLAND ATOMIC ENERGY COMMISSION Nuclear Science Center South Ferry Road Narragansett, R. I. 02882

January 23, 1991

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

License No. R-95 Docket No. 50-193

Dear Sirs:

This letter will confirm the telephone report made by me to the Nuclear Regulatory Commission Duty Officer at about 12:30 pm on January 16, 1991. The report concerned the complete loss of our telephone services, including both voice and burglar/supervisory alarm systems.

The loss included our four voice telephone lines, burglar and supervisory alarm systems monitored by the ADT Protective Company and the redundant burglar alarm system monitored by the Narragansett Police. The failure occurred at approximately 11:30 am, and was caused by the telephone lines being cut through while installing telephone poles.

Contact with Rhode Island Emergency Management Agency was verified using the installed two-way radio. RIEMA provided 24 hour monitoring of the communication link. A member of our staff remained after hours to maintain surveillance.

All telephone services were restored to normal at 9:00 am, January 18, 1991. There were no consequences at the facility.

Very truly yours,

W. Simoneau

Acting Assistant Director

W. Janouesen

Cut No P871839762

Add: NRR/DRIS/RSGB 1