

HADDAM NECK PLANT 362 INJUN HOLLOW ROAD • EAST HAMPTON, CT 06424-3099

February 15, 1994

SUBJECT: Connecticut Yankee Monthly Operating Report 94-01, January 1994

The enclosed Summary Of Plant Operations was inadvertently omitted from the Connecticut Yankee Monthly Operating Report #94-01 for January 1994.

We would appreciate it if you would insert it into the report and sincerely apologize for any inconvenience.

Thank you.

Vicki Allen

Administration, Connecticut Yankee

220117

TYPE REV. 2 TO

1524

The following is a Summary of Plant Operations for January 1994.

On January 1st, at 0000 hours, the plant was in Mode 1, Power Operation at 100% load.

On January 13th at 0502 hours, a shutdown was commenced due to the rod position indication for rods 34, 35 and 36 being inoperable. At 0632 hours, the load reduction was halted at approximately 75% power, when the rod position drawer was repaired. At 0634 hours, the plant commenced a power ascension. At 0634 hours, the plant commenced a power ascension. At 0810 hours, the power ascension was stopped due to the RMS-14 indication of a degasifier problem. At 1813 hours, the incident on the degasifier had been evaluated and the system was returned to operation. At this time a load increase was re-initiated. At 2048 hours, the plant was at 100% load.

On January 20th at 1616 hours, a load reduction was commenced due to fluctuating temperatures on the main generator hydrogen coolers. At 1640 hours, the load reduction was stopped at 90% after finding the temperature controller for the hydrogen cooler control valve SW-TCV-1117 had failed. SW-TCV-1117 was placed in manual control and temperatures returned to normal. At 1646 hours, a load increase was commenced. At 1915 hours, load was at 100%.

The following is a Summary of Plant Operations for January 1994.

On January 1st, at 0000 hours, the plant was in Mode 1, Power Operation at 100% load.

On January 13th at 0502 hours, a shutdown was commenced due to the rod position indication for rods 34, 35 and 36 being inoperable. At 0632 hours, the load reduction was halted at approximately 75% power, when the rod position drawer was repaired. At 0634 hours, the plant commenced a power ascension. At 0634 hours, the plant commenced a power ascension. At 0810 hours, the power ascension was stopped due to the RMS-14 indication of a degasifier problem. At 1813 hours, the incident on the degasifier had been evaluated and the system was returned to operation. At this time a load increase was re-initiated. At 2048 hours, the plant was at 100% load.

On January 20th at 1616 hours, a load reduction was commenced due to fluctuating temperatures on the main generator hydrogen coolers. At 1640 hours, the load reduction was stopped at 90% after finding the temperature controller for the hydrogen cooler control valve SW-TCV-1117 had failed. SW-TCV-1117 was placed in manual control and temperatures returned to normal. At 1646 hours, a load increase was commenced. At 1915 hours, load was at 100%.

The following is a Summary of Plant Operations for January 1994.

On January 1st, at 0000 hours, the plant was in Mode 1, Power Operation at 100% load.

On January 13th at 0502 hours, a shutdown was commenced due to the rod position indication for rods 34, 35 and 36 being inoperable. At 0632 hours, the load reduction was halted at approximately 75% power, when the rod position drawer was repaired. At 0634 hours, the plant commenced a power ascension. At 0634 hours, the plant commenced a power ascension. At 0810 hours, the power ascension was stopped due to the RMS-14 indication of a degasifier problem. At 1813 hours, the incident on the degasifier had been evaluated and the system was returned to operation. At this time a load increase was re-initiated. At 2048 hours, the plant was at 100% load.

On January 20th at 1616 hours, a load reduction was commenced due to fluctuating temperatures on the main generator hydrogen coolers. At 1640 hours, the load reduction was stopped at 90% after finding the temperature controller for the hydrogen cooler control valve SW-TCV-1117 had failed. SW-TCV-1117 was placed in manual control and temperatures returned to normal. At 1646 hours, a load increase was commenced. At 1915 hours, load was at 100%.

The following is a Summary of Plant Operations for January 1994.

On January 1st, at 0000 hours, the plant was in Mode 1, Power Operation at 100% load.

On January 13th at 0502 hours, a shutdown was commenced due to the rod position indication for rods 34, 35 and 36 being inoperable. At 0632 hours, the load reduction was halted at approximately 75% power, when the rod position drawer was repaired. At 0634 hours, the plant commenced a power ascension. At 0634 hours, the plant commenced a power ascension. At 0810 hours, the power ascension was stopped due to the RMS-14 indication of a degasifier problem. At 1813 hours, the incident on the degasifier had been evaluated and the system was returned to operation. At this time a load increase was re-initiated. At 2048 hours, the plant was at 100% load.

On January 20th at 1616 hours, a load reduction was commenced due to fluctuating temperatures on the main generator hydrogen coolers. At 1640 hours, the load reduction was stopped at 90% after finding the temperature controller for the hydrogen cooler control valve SW-TCV-1117 had failed. SW-TCV-1117 was placed in manual control and temperatures returned to normal. At 1646 hours, a load increase was commenced. At 1915 hours, load was at 100%.

The following is a Summary of Plant Operations for January 1994.

On January 1st, at 0000 hours, the plant was in Mode 1, Power Operation at 100% load.

On January 13th at 0502 hours, a shutdown was commenced due to the rod position indication for rods 34, 35 and 36 being inoperable. At 0632 hours, the load reduction was halted at approximately 75% power, when the rod position drawer was repaired. At 0634 hours, the plant commenced a power ascension. At 0634 hours, the plant commenced a power ascension. At 0810 hours, the power ascension was stopped due to the RMS-14 indication of a degasifier problem. At 1813 hours, the incident on the degasifier had been evaluated and the system was returned to operation. At this time a load increase was re-initiated. At 2048 hours, the plant was at 100% load.

On January 20th at 1616 hours, a load reduction was commenced due to fluctuating temperatures on the main generator hydrogen coolers. At 1640 hours, the load reduction was stopped at 90% after finding the temperature controller for the hydrogen cooler control valve SW-TCV-1117 had failed. SW-TCV-1117 was placed in manual control and temperatures returned to normal. At 1646 hours, a load increase was commenced. At 1915 hours, load was at 100%.

The following is a Summary of Plant Operations for January 1994.

On January 1st, at 0000 hours, the plant was in Mode 1, Power Operation at 100% load.

On January 13th at 0502 hours, a shutdown was commenced due to the rod position indication for rods 34, 35 and 36 being inoperable. At 0632 hours, the load reduction was halted at approximately 75% power, when the rod position drawer was repaired. At 0634 hours, the plant commenced a power ascension. At 0634 hours, the plant commenced a power ascension. At 0810 hours, the power ascension was stopped due to the RMS-14 indication of a degasifier problem. At 1813 hours, the incident on the degasifier had been evaluated and the system was returned to operation. At this time a load increase was re-initiated. At 2048 hours, the plant was at 100% load.

On January 20th at 1616 hours, a load reduction was commenced due to fluctuating temperatures on the main generator hydrogen coolers. At 1640 hours, the load reduction was stopped at 90% after finding the temperature controller for the hydrogen cooler control valve SW-TCV-1117 had failed. SW-TCV-1117 was placed in manual control and temperatures returned to normal. At 1646 hours, a load increase was commenced. At 1915 hours, load was at 100%.

The following is a Summary of Plant Operations for January 1994.

On January 1st, at 0000 hours, the plant was in Mode 1, Power Operation at 100% load.

On January 13th at 0502 hours, a shutdown was commenced due to the rod position indication for rods 34, 35 and 36 being inoperable. At 0632 hours, the load reduction was halted at approximately 75% power, when the rod position drawer was repaired. At 0634 hours, the plant commenced a power ascension. At 0634 hours, the plant commenced a power ascension. At 0810 hours, the power ascension was stopped due to the RMS-14 indication of a degasifier problem. At 1813 hours, the incident on the degasifier had been evaluated and the system was returned to operation. At this time a load increase was re-initiated. At 2048 hours, the plant was at 100% load.

On January 20th at 1616 hours, a load reduction was commenced due to fluctuating temperatures on the main generator hydrogen coolers. At 1640 hours, the load reduction was stopped at 90% after finding the temperature controller for the hydrogen cooler control valve SW-TCV-1117 had failed. SW-TCV-1117 was placed in manual control and temperatures returned to normal. At 1646 hours, a load increase was commenced. At 1915 hours, load was at 100%.

The following is a Summary of Plant Operations for January 1994.

On January 1st, at 0000 hours, the plant was in Mode 1, Power Operation at 100% load.

On January 13th at 0502 hours, a shutdown was commenced due to the rod position indication for rods 34, 35 and 36 being inoperable. At 0632 hours, the load reduction was halted at approximately 75% power, when the rod position drawer was repaired. At 0634 hours, the plant commenced a power ascension. At 0634 hours, the plant commenced a power ascension. At 0810 hours, the power ascension was stopped due to the RMS-14 indication of a degasifier problem. At 1813 hours, the incident on the degasifier had been evaluated and the system was returned to operation. At this time a load increase was re-initiated. At 2048 hours, the plant was at 100% load.

On January 20th at 1616 hours, a load reduction was commenced due to fluctuating temperatures on the main generator hydrogen coolers. At 1640 hours, the load reduction was stopped at 90% after finding the temperature controller for the hydrogen cooler control valve SW-TCV-1117 had failed. SW-TCV-1117 was placed in manual control and temperatures returned to normal. At 1646 hours, a load increase was commenced. At 1915 hours, load was at 100%.

The following is a Summary of Plant Operations for January 1994.

On January 1st, at 0000 hours, the plant was in Mode 1, Power Operation at 100% load.

On January 13th at 0502 hours, a shutdown was commenced due to the rod position indication for rods 34, 35 and 36 being inoperable. At 0632 hours, the load reduction was halted at approximately 75% power, when the rod position drawer was repaired. At 0634 hours, the plant commenced a power ascension. At 0634 hours, the plant commenced a power ascension. At 0810 hours, the power ascension was stopped due to the RMS-14 indication of a degasifier problem. At 1813 hours, the incident on the degasifier had been evaluated and the system was returned to operation. At this time a load increase was re-initiated. At 2048 hours, the plant was at 100% load.

On January 20th at 1616 hours, a load reduction was commenced due to fluctuating temperatures on the main generator hydrogen coolers. At 1640 hours, the load reduction was stopped at 90% after finding the temperature controller for the hydrogen cooler control valve SW-TCV-1117 had failed. SW-TCV-1117 was placed in manual control and temperatures returned to normal. At 1646 hours, a load increase was commenced. At 1915 hours, load was at 100%.

The following is a Summary of Plant Operations for January 1994.

On January 1st, at 0000 hours, the plant was in Mode 1, Power Operation at 100% load.

On January 13th at 0502 hours, a shutdown was commenced due to the rod position indication for rods 34, 35 and 36 being inoperable. At 0632 hours, the load reduction was halted at approximately 75% power, when the rod position drawer was repaired. At 0634 hours, the plant commenced a power ascension. At 0634 hours, the plant commenced a power ascension. At 0810 hours, the power ascension was stopped due to the RMS-14 indication of a degasifier problem. At 1813 hours, the incident on the degasifier had been evaluated and the system was returned to operation. At this time a load increase was re-initiated. At 2048 hours, the plant was at 100% load.

On January 20th at 1616 hours, a load reduction was commenced due to fluctuating temperatures on the main generator hydrogen coolers. At 1640 hours, the load reduction was stopped at 90% after finding the temperature controller for the hydrogen cooler control valve SW-TCV-1117 had failed. SW-TCV-1117 was placed in manual control and temperatures returned to normal. At 1646 hours, a load increase was commenced. At 1915 hours, load was at 100%.

The following is a Summary of Plant Operations for January 1994.

On January 1st, at 0000 hours, the plant was in Mode 1, Power Operation at 100% load.

On January 13th at 0502 hours, a shutdown was commenced due to the rod position indication for rods 34, 35 and 36 being inoperable. At 0632 hours, the load reduction was halted at approximately 75% power, when the rod position drawer was repaired. At 0634 hours, the plant commenced a power ascension. At 0634 hours, the plant commenced a power ascension. At 0810 hours, the power ascension was stopped due to the RMS-14 indication of a degasifier problem. At 1813 hours, the incident on the degasifier had been evaluated and the system was returned to operation. At this time a load increase was re-initiated. At 2048 hours, the plant was at 100% load.

On January 20th at 1616 hours, a load reduction was commenced due to fluctuating temperatures on the main generator hydrogen coolers. At 1640 hours, the load reduction was stopped at 90% after finding the temperature controller for the hydrogen cooler control valve SW-TCV-1117 had failed. SW-TCV-1117 was placed in manual control and temperatures returned to normal. At 1646 hours, a load increase was commenced. At 1915 hours, load was at 100%.