Kairbanks Memorial Hospital

1650 Cowles St. FAIRBANKS, ALASKA 99701 1982 1104 24 PM 12: 43

REGION VIAE

OPERATED BY LUTHERAN HOSPITALS AND HOMES SOCIETY FARGO, NORTH DAKOTA 58102

November 18, 1982

H. E. Book, Chief Radiologic Safety Branch United States Nuclear Regulatory Commission Region V 1450 Maria Lane, Suite 210 Walnut Creek, California 94596

ATTN: Beth Reidlinger

Dear Ms. Reidlinger:

Today, the Nuclear Medicine Technician informed me of your telephone call requesting an answer to the letter from NRC dated 10/6/82 requesting a linearity test on the Capintec CRC-6 Dose Calibrator. Please find the attached letter to H. E. Book dated October 28, 1982 and the attached linearity test, dated October 12, 1982. The attached response to your initial letter was mailed on October 29, 1982 and addressed to H. E. Book. I would assume the letter is either lost in the Postal service or is somewhere in the Walnut Creek division in H. E. Book's file. I sincerely hope the attached file copy will suffice.

Since the attached linear calibration check was performed, a replacement dose calibrator has been obtained from Capintec while the Department's dose calibrator is undergoing linearity testing and repair by the Capintec facility. We are planning to perform an in-house linearity test on Monday of next week when the new Technetium generator arrives.

I sincerely hope this cover letter will answer the requirements of the NRC related to your original letter dated October 6, 1982.

Sincerely yours,

and felm m

Roger D. Fellows, M.D. Radiologist

RDF:cac Attachments (NRC)

8212060271 821130 NMS LIC30 50-13648-01 PDR