LICENSEE EVENT REPORT

	CONTROL BLOCK:	ASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N Y J A F 1 2 0 0 - 0 0 0 0 - 0	0 0 0 3 4 1 1 1 1 4 57 CAT 58 5
CON'T 0 1 7 8	REFORT L 6 0 5 0 0 0 3 3 3 7 1 1 SOURCE 60 61 DOCKET NUMBER 68 69	0 2 7 8 2 8 1 1 2 3 8 2 9 EVENT DATE 80
0 2	During a review of TS surveillance re	quirements, it was noted that no
0 3	procedure had been issued to satisfy	Appendix A paragraph 4.3.A.2.F.
0 4	This specification requires the scram	discharge volume vents and drain
0 5	to be cycled on a quarterly basis. A	further review indicates that the
0 6	surveillance was not performed at the	required frequency. The test
0 7	was accomplished prior to startup in	March, 1982 and again when this
0 8	condition was discovered on October 2	27, 1982. No health/safety hazard 80
0 9	SYSTEM CODE CODE SUBCODE SUBCODE OF A IS SUBCODE SUBCODE OF A IS SUBCODE SUBCODE OF A IS SUBCODE OF A IS SEQUENTIAL	SUBCODE SUBCOD
	17 REPORT EVENT YEAR REPORT NO.	TYPE NO. 1 0 3 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
	ACTION FUTURE CEFFECT SHUTDOWN METHOD HOURS 22 OF STREET SHUTDOWN METHOD HOURS 22 OF S	ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER Y 23 N 24 Z 25 Z 0 0 0 0 26 41 42 43 43 47
10	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)	of supervisory personnel to
111	recognize the added surveillance requ	
1 2	Amendment 62. A surveillance procedu	ire has since been developed and
1 3	the valves have been cycled successfu	illy. Adequate procedure controls
1 4	are in effect to control Technical Sp	pecification changes (See Attached)
7 8	FACILITY STATUS & POWER OTHER STATUS 30 METHOD OF DISCOVERY NA A 3	DISCOVERY DESCRIPTION (32)
1 6	ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA 45	NA SO
7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA	80
7 8	PERSONNEL INJURIES 13 NUMBER DESCRIPTION 41	
7 8	DO O O O O O O O O O O O O O O O O O O	12060296 821123 R ADDCK 05000333
1 9	TYPE DESCRIPTION S	PDR
2 0	PUBLICITY ISSUED DESCRIPTION (45) NA	NRC USE ONLY
2 8	NAME OF PREPARER R. Liseno	PHONE: 342-3840

POWER AUTHORITY OF THE STATE OF NEW YORK JAMES A. FITZPATRICK NUCLEAR POWER PLANT

DOCKET NO. 50-333

ATTACHMENT TO LER - 82-049/03L-0

PAGE 1 of 1

Amendment No. 62, as received at the site, contained some administrative errors. (e.g., some of the changes did not have revision bars to indicate it was a change) The Licensing Organization of the Power Authority has committed to doing an administrative review of Technical Specification Amendments and informing the JAF staff when they detect an error.

This review is in addition to the reviews that are required by each of the Department Superintendents at the plant.