	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 7 8	N J S G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 EICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
0 1 7 8	REPORT L 6 0 5 0 0 0 2 7 2 7 1 1 1 3 8 2 8 1 1 1 7 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	On November 13, 1982, No. 12 Station Power Transformer was de-energized for planned
0 3	maintenance. Due to the resulting loss of the Nos. F and G Group Buses, the automatic
0 4	starting feature of both Nos. 1 and 2 Diesel Fire Pumps was disabled. The fire pumps
0 5	were declared inoperable, and Action Statement 3.7.10.1b was entered. The manual
0 6	starting capability remained operable, and an operator was stationed locally to start
0 7	the pump if required. Action Statement 3.7.10.1b requires a prompt report with 14 day
0 8	followup pursuant to Technical Specification 6.9.2.
7 8	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC
7 8	9 10 11 12 13 18 19 20 SEQUENTIAL OCCURRENCE REPORT REVISION
	17 REPORT 8 2 0 8 5 0 1 T 0 0 0 0 0 0 0 0 0
	ACTION FUTURE COMPONENT SUBMITTED FORM SUB. PRIME COMP. SUPPLIER S
1 0	Maintenance on No. 12 Station Power Transformer was completed, the fire pump auto-
111	matic starting feature was restored to operation, and the action statement was
1 2	terminated.
1 3	(82-076, 82-035, 82-027, 82-019, 81-093)
7 8	9
	FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 N/A A Planned Maintenance
	9 10 12 13 44 45 46 RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 N/A LOCATION OF RELEASE 36 N/A
7 8	9 10 11 44 45 80 PERSONNEL EXPOSURES
1 7 8	NUMBER O 37 Z 38 DESCRIPTION (39) 9 PERSONNEL INJURIES 13 80
1 8	O O O O O N/A
1 9	SO TYPE DESCRIPTION N/A
7 8	9 10 8212060308 821117 80 PUBLICITY 60 PDP ADDCK 05000272 NRCUSE ONLY
2 0 7 8	PDR SSUED DESCRIPTION 49 N/A S PDR S 68 69 80 5
	NAME OF PREPARER PHONE PHONE