

DCB/DCB

**syncor**

January 28, 1991

William H. Schultz  
Nuclear Materials Safety  
Section I  
U.S.N.R.C, Region III  
799 Roosevelt Road  
Glen Ellyn, Ill 60137

Dear Mr. Schultz:


Re: Lic. # 34-19008-01MD  
Doc. # 030-15203

The following is response to the violation cited in your letter to Steve Shipper dated January 15, 1991.

In order to prevent future dispensing of incorrect pharmaceutical form, use of the "see-through" vial shields will continue. All labels identifying the vial shield of particular products will be removed. Only a label identifying the isotope, lot #, etc. will remain. Thus a new label is applied every time a product is compounded. The cold vials will not be placed in the vial shield until they are ready to be compounded. Whenever another pharmacist or technecian is present, they will double check the vial being prepared as what the preparer believes it to be. Dispensers have been re-instructed to look at the vial inside the shield before dispensing. The above corrective procedures have already been place since November 27, 1990.

If you have any further questions or comments, please contact me.

Sincerely,

  
Kamal Amin, R.Ph

cc: Frank Comer, Corporate RSO  
Randy Asmus, Regional Manager  
Steve Shipper, Sr. Pharmacy Manager

FEB 1 1991



*Innovators in high-tech pharmacy services*

9102120005 910128  
REG LIC30  
34-19008-01MD PDR

Syncor International Corporation • 2719 Manchester Road • Akron, OH 44319  
Medical Services Group • (216) 753-1009

IE 07