

APPENDIX A

NOTICE OF VIOLATION

Baltimore Gas and Electric Company
Calvert Cliffs Unit 2

Docket/License: 50-318/DPR-69

As a result of the inspection conducted on October 12 - November 9, 1982, and in accordance with the NRC Enforcement Policy (10CFR2 Appendix C) published in the Federal Register on March 9, 1982 (47FR9987), the following violation was identified:

Technical Specification 3.0.4 requires that entry into an Operational Mode not be made unless applicable Limiting Conditions for Operation are met. Technical Specification 3.9.2 requires, as a Limiting Condition for Operation for Mode 6 (refueling), that two source range neutron flux monitors be operating, each with continuous visual indication in the Control Room and one with audible indication in the Control Room.

Contrary to the above, from October 21 to October 25, 1982, Unit 2 was placed in Mode 6 without an operable audible indication of source range neutron flux in the Control Room.

This is a Severity Level IV Violation (Supplement I).

Pursuant to 10CFR2.201, Baltimore Gas and Electric Company is hereby required to submit to this office, within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.

8212100010 821124
PDR ADOCK 05000317
G PDR

OFFICE
SURNAME
DATE