

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 788 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

DCP (PLDS)

FEL 5 1891

Docket No. 50-295 Docket No. 50-304

Commonwealth Edison Company ATTN: Mr. Cordell Reed Senior Vice President Opus West III 1400 Opus Place - Suite 300 Downers Grove, IL 60515

Gentlemen:

This refers to the routine safety inspection conducted by J. D. Smith, R. J. Leemon, and A. M. Bongiovanni of this office from December 9, 1990 through January 14, 1991 of activities at the Zion Nuclear Generating Station, authorized by License Numbers DPR-39 and DPR-48, and to the discussion of our findings with Mr. T. Joyce at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements; however, the licensee-identified violation is not being cited because the criteria specified in 10 CFR Part 2, Appendix C, Section V.G.1 of the Enforcement Policy were satisfied.

While we have noted improvements in control room staff performance which may be attributable, in part, to the control room reorganization. we are concerned by the continuing lack of control room visibility and oversight by senior operations management. A recent example of this was observed during the Safety Injection pump surveillance failure event of January 4, 1991, and is discussed in this report. We highlight this and encourage your attention because we view an active senior management as essential in communicating expectations to the line organization.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

9102120082 910205 PDR ADOCK 05000295 G PDR Commonwealth Edison Company

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

1:00 in William L. Forney, Deputy Director Division of Reactor Projects

Enclosure: Inspection Reports No. 50-295/90033(DRP); No. 50-304/90033(DRP)

Distribution

cc w/enclosure: M. J. Wallace, Vice President, PWR Operations T. Kovach, Nuclear Licensing Manager T. Joyce, Station Manager Chandu Patel, Project Manager, NRR W. L. Axelson, RIII R. N. Gardner, RIII R. Barrett, NRR J. W. Craig, NRR C. M. Trammell, NRR R. Greger, RIII DCD/DCB (RIDS) Licensing Fee Management Branch Resident Inspectors: Bryon, Braidwood, Zion J. Creed, Chief, Safeguards Section RIII Richard Hubbard J. W. McCaffrey, Chief, Public Utilities Division Mayor, City of Zion

2