

NOTICE OF VIOLATION

Kraus & Krisunas
Grand Rapids, Michigan

License No. 21-20482-01
Docket No. 030-18430

As a result of the inspection conducted on January 15, 1991, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, (1990) (Enforcement Policy) the following violations were identified:

1. License Condition No. 12(A)(1) requires that sealed sources be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above, the licensee failed to test sealed sources for leakage and/or contamination at intervals not to exceed six months. Specifically, from February 19, 1986, to March 6, 1990, the licensee's Troxler Model 3411 moisture/density gauge was not leak tested.

This is a Severity Level IV violation (Supplement VI).

This is a repeat violation.

2. License Condition No. 14 requires the licensee to conduct a physical inventory every six months to account for all gauges received and possessed under the license.


Contrary to the above, from approximately March 1986, the licensee has failed to conduct a physical inventory every six months to account for all gauges received and possessed under the license.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of this Notice a written statement or explanation in reply, including for each violation: (1) the corrective steps that have been taken and the results achieved; (2) the corrective steps that will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

FEB 05 1991

Dated _____



Roy S. Caniano, Chief
Nuclear Materials Safety
Section 2

9102120137 910205
REG3 LIC30
21-20482-01 PDR