



Wisconsin Electric POWER COMPANY
231 W. MICHIGAN, P.O. BOX 2046, MILWAUKEE, WI 53201

December 3, 1982

Mr. J. G. Keppler, Regional Administrator
Office of Inspection and Enforcement,
Region III
U. S. NUCLEAR REGULATORY COMMISSION
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

DOCKET NO. 50-266
LICENSEE EVENT REPORT NO. 82-022/01T-0
POINT BEACH NUCLEAR PLANT, UNIT 1

Enclosed is Licensee Event Report No. 82-022/01T-0 (a 14-day follow-up report) with an attachment which provides a description of an event reportable in accordance with Technical Specification 15.6.9.2.A.3, "Abnormal degradation discovered in fuel cladding, reactor coolant pressure boundary, or primary containment."

This Licensee Event Report was not completed within the required 14-day period because it was delayed until all the foreign objects were retrieved and repairs completed such that a complete report could be filed. The last objects were retrieved and final inspection performed late during the day of November 24, 1982 (the day before the Thanksgiving holiday weekend).

Very truly yours,

Assistant Vice President

C. W. Fay

Enclosure

Copy to NRC Resident Inspector

8212100224 821203
PDR ADOCK 05000266
S PDR

DEC 6 1982

IE 22