

Appendix

NOTICE OF VIOLATION

Reuter-Stokes, Inc.

License No. SNM-1826

As a result of the inspection conducted on June 21 through 25, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

License Condition No. 15 required that license material be possessed and used in accordance with statements, representations, and procedures contained in application dated May 26, 1978. Item 7.5, page 22 of the application, states that "the film badge service monitors for x-ray, gamma, beta, and fast neutrons".


Contrary to the above, the NRC inspector determined through statements of the licensee representatives and a review of records that two individuals were issued film badges for the period December 1, 1980 to December 1, 1981 which did not monitor for fast neutrons. It was noted that these two individuals had been working with a 0.83 curie PuBe neutron source at various times during this period.

This is a Severity Level IV violation (Supplement VI).

The inspection showed that action had been taken to correct the identified item of noncompliance and to prevent recurrence. Consequently, no reply to this item of noncompliance is required and we have no further questions regarding this matter.

Dated

12/2/82


D. J. Sreniawski, Chief
Materials Radiation Protection
Section 2

8212100249 821202
PDR ADOCK 07002872
C PDR