



Department of Energy  
Albuquerque Field Office  
P.O. Box 5400  
Albuquerque, New Mexico 87185-5400

FEB 02 1991

Mr. John J. Surmeier, Chief  
Uranium Recovery Branch  
Division of Low-Level Waste  
Management & Decommissioning  
Office of Nuclear Materials Safety  
and Safeguards  
U.S. Nuclear Regulatory Commission  
Mail Stop 5E-4 OWFN  
Washington, DC 20555

Dear Mr. Surmeier:

Enclosed for your review and concurrence are two copies of Revision 1, Review D, to the Remedial Action Inspection Plan (RAIP) for the Mexican Hat, Utah, Monument Valley, Arizona, Uranium Mill Tailings Remedial Action (UMTRA) Project site. We believe the RAIP adequately addresses inspection activities and is consistent with the following:

- o Remedial Action Plan
- o Design specifications
- o UMTRA Project quality assurance program requirements
- o U.S. Nuclear Regulatory Commission's Staff Technical Position  
Revision 2 on testing and inspection plans

Should you have any questions, please contact Milt Scoutaris of my staff at (505) 845-5630.

Sincerely,

Frank Bosiljevac  
Technical Support Group Leader  
Uranium Mill Tailings Remedial Action  
Project Office

Enclosure

cc:  
See page 2

9403040339 940202  
PDR WASTE  
WM-63 PDR

delete: LA

WM-63  
WM-70  
NK04

Mr. John J. Surmeier

2

FFB 02 1994

cc w/enclosure:

F. Bosiljevac, UMTRA

M. Scoutaris, UMTRA

R. Edge, UMTRA

cc w/o enclosure:

C. Smythe, UMTRA

J. McBee, TAC

R. Bennett, TAC

S. Martz, MK-F