

NJK-82-547

December 1, 1982

J. Keppler, Regional Administrator Office of Inspection and Enforcement Region III U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Reference: Quad-Cities Nuclear Power Station

Docket Number 50-265, DPR-30, Unit Two

Appendix A, Section 3.9.E.1

Enclosed please find Supplemental Reportable Occurrence Report Number RO 82-18/03L-1 for Quad-Cities Nuclear Power Station. This is submitted to correct an error, in that both heat exchangers were replaced, not just one.

This report is submitted to you in accordance with the requirements of Technical Specification 6.6.B.2.b; operation in a degraded mode permitted by a limiting condition of operation.

Respectfully,

COMMONWEALTH EDISON COMPANY OUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivianakis Station Superintendent

N'S Kurrowikh

NJK: HGL/bb

Enclosure

cc T. J. Rausch N. Chrissotimos INPO Records Center

8212100328 821201 PDR ADDCK 05000265

DEC 6 1982 TELL