50.55(e) Report

Arizona Public Service Company

P.O. BOX 21666 . PHOENIX, ARIZONA 85036

1582 DEC -8 FM 12 32

EGION VICE

November 29, 1982 ANPP-22404-GHD/BSK

U. S. Nuclear Regulatory Commission Region V Creekside Oaks Office Park 1450 Maria Lane - Suite 210 Walnut Creek, California 94596-5368

Attention: Mr. D. M. Sternberg, Chief Reactor Projects Branch 1

Subject: Deficiency Evaluation Report 82-64

A 50.55(e) Evaluation Relating to Dissimilar-Metal Socket Welds Restricted By Revision 10 of PM-204 Were Installed Due

to Delay In Revising Drawings

File: 82-019-026 D.4.33.2

Reference: Telephone Conversation between A. D'Angelo and

G. Duckworth on October 29, 1982

Dear Sir:

The NRC was notified of the subject Deficiency Evaluation in the referenced telephone conversation, with a determination of reportability to be made within thirty (30) days (November 29, 1982).

The deficiency has subsequently been determined to be Not Reportable under the requirements of 10CFR50.55(e), therefore, no written report is required. Necessary documentation of the evaluation will be maintained in APS files.

Very truly yours,

E. E. Van Brunt, Jr. APS Vice President

Nuclear Projects Management

E. E Vace Ponce F

ANPP Project Director

EEVBJr/GHD:db

cc: See Attached Page 2

IE27

U. S. Nuclear Regulatory Commission Attention: Mr. D. M. Sternberg, Chief Page 2

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.

J. A. Roedel

D. B. Fasnacht

G. C. Andognini

A. C. Rogers

B. S. Kaplan

W. E. Ide

J. Vorees

J. A. Brand

A. C. Gehr

W. J. Stubblefield

W. G. Bingham

R. L. Patterson

R. W. Welcher

R. M. Grant

D. R. Hawkinson

L. E. Vorderbrueggen

G. A. Fiorelli

J. R. Bynum

Lynne Bernabei, Esq. Harmon & Weiss 1725 "I" Street, NW Washington, D. C. 20006

R. L. Greenfield Assistant Attorney General Bataan Memorial Building Santa Fe, New Mexico 87503