

P.O. BOX 1934

ROCK SPRINGS, WYOMING 82901

(307) 382-5281

January 30, 1991

United States Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Dr., Suite 1000
Arlington, TX 76011
ATTN: A. Bill Beach, Director
Division of Radiation Safety and Safeguards

Subject: License #49-21178-01 Docket #30-19877/90-01

Dear Sir,

The corrective steps we have taken to avoid further violations on items one, two and four are as follows:

Item 1 & 2: Sealed source testing and radiation survey instrument calibration has resumed as of January 1990 as seen on the enclosed form.

Item 4: Labels were printed for the purpose of proper labeling of transportation packages. I have enclosed said label.

Item three was addressed in our letter dated September 13, 1990. If further explanation is needed let me know.

Sincerely,

POMRENKE WIRELINE SERVICES, INC.

Nick E. Pomrenke

President

NEP/bap encl. USA DOT 7A

TYPE A

9102130216 910130

RE04 LIC30 178-01 PDR

CASED HOLE LOGGING

JET PERFORATING

IF-07



P.O. BOX 1934

ROCK SPRINGS, WYOMING 82901

(307) 382-5281

January 1, 1990		Janua	ary 1, 1991
	Area Monitered Inventory Calculation Leak Test Instrument Calibration Semi-Annual Report Annual Safety Review Annual Inspection Check List Signature		Source Inventory  Area Monitered  Inventory Calculation  Leak Test  Instrument Calibration  Semi-Annual Report  Annual Safety Review  Annual Inspection  Check List  Signature
	Source Inventory  Area Monitered  Inventory Calculation  Leak Test  Instrument Calibration  Semi-Annual Report  Annual Safety Review 1-1-70  Annual Inspection  Check List		1, 1990 Source Inventroy_ Area Monitered_ Inventory Calculation_ Leak Test_ Instrument Calibration_ Semi-Annual Report_ Annual Safety Review_ Annual Inspection Check List
	Signature Stant Pombe Hss	100	Signature