

Appendix

NOTICE OF VIOLATION

Interpoll, Incorporated

License No. 22-19911-01

30-19513

As a result of the inspection conducted on November 24, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violations were identified:

1. License Condition No. 12 requires that licensed material shall be used by or under the supervision of, certain named individuals.

Contrary to the above, the individuals named on the license are no longer employed by your corporation. The licensed material is no longer under their supervision and thus constitutes unauthorized use of byproduct material.

This is a Severity Level IV violation (Supplement VI).


2. License Condition No. 13 requires that your chromatograph detector containing nickel-63 be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to this requirement, you failed to test your chromatograph detector containing nickel-63 for contamination or leakage since September 1981, a period greater than six months.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

12-13-82
Dated


D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1

8212210471 821214
NMS LIC30
22-19911-01 PDR