In Reply Refer To: License: 35-13341-01 Docket: 030-02925/91-01

Radiology of Eastern Oklahoma, Inc. ATTN: Avery Paul Compton, M.D. Warren Professional Bldg., Suite 507 6465 S. Yale Tulsa, Oklahoma 74136

## Gentlemen:

This refers to the routine, unannounced radiation safety inspection conducted by Mr. Richard A. Leonardi, Jr., of this office on January 7, 1991, of the activities authorized by NRC Byproduct Material License No. 35-13341-01, and to the discussion of our findings held by the inspector with members of your staff at the conclusion of the inspection.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observations by the inspector.

The inspector observed that this facility represents one of the licensee's three diagnostic facilities in Tulsa. The facility is the only one of the three that provides nuclear medicine services. The inspector noted that the licensee performs about 80 nuclear medicine procedures per month with three iodine-131 therapy procedures (less than 30 millicuries) being performed per month. The inspector noted that licensed materials had been properly received and stored with adequate consideration being given to material security and licensed material disposal.

During this inspection, certain of your activities were found not to be conducted in full compliance with NRC requirements. Consequently, you are required to respond to this matter in writing, in accordance with the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Your response should be based on the specifics contained in the Notice of Violation enclosed with this letter.

RIV: NMSIS UNC RLeonardi: sar 1/2/91

C:NMSISCLC. CLCain /2491 D:DRSS ABBeach 2/

9102140033 910128 REG4 LIC30 35-13341-01 PDR