	Page 1 of 1
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	M S G G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 6 57 CAT 58
CON'T	REPORT L 6 0 5 0 0 0 4 1 6 7 1 1 2 9 8 2 8 1 2 2 8 8 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	On November 29, 1982, a Q. A. audit revealed that beginning on September 23, during
0 3	periods when the plant was in Hot Shutdown, the Containment to Auxiliary Building
0 4	differential pressure was verified every 24 hours instead of every 12 hours as
0 5	required by T.S.4.6.1.7. In accordance with T.S.4.0.3 this is being reported
0 6	pursuant to T.S.6.9.1.13.b. The event had no effect on the health and safety of the
0 7	public and did not constitute a threat to plant safety.
08	9 80
0 9 7 8	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	SEQUENTIAL REPORT TYPE REVISION NO. 17 REPORT NUMBER 21 22 24 26 27 28 29 30 31 32
	ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER SUPPLIER
1 0	The cause was personnel error. A review of procedures in Operations Log O6-OP-1000-D-
11	0001 Rev. 16 confirmed that the surveillance procedures and the requirements in T.S.
1 2	4.6.1.7 are in agreement. Operations personnel were made aware of their error via QA
1 3	Monitoring Audit Report, MAR-82/103, and were instructed accordingly. This is a
1 4	final report.
15	STATUS STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 B 25 0 0 0 0 29 NA C 31 Quality Assurance Audit OCTIVITY CONTENT 12 13 44 45 46 80
	ELEASED OF HE EASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) NA 10 11 44 45 80
U.	OLOLO 37 Z 38 DESCRIPTION (9) NA PERSONNEL INJURIES 13
1 B	NOMBE DESCRIPTION (41) NA NA 80
	LOSS OF GRIDAMA SE TO FACILITY (43)
7 8	NA 8301040124 821228 NBC USE ONLY
2 0	PUBLICITY PER ADOCK 05000416 S PDR ADOCK 05000416 PDR 68 69 80 2
	NAME OF PREPARER Original signed by Matthew V. Rohrer PHONE