



January 28, 1991

A. Bill Beach, Director
Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Tx. 76011

Re: Docket:150-00042/90-04

Mr. Beach:

In response to your letter dated December 24, 1990, this office wishes to be in full compliance with the policy and procedures of the Nuclear Regulatory Commission and the Texas Regulations for Control of Radiation (TRCR).

The response of Robco Production Logging, Inc. is as follows:

A. TRCR part 36.403: a copy of Texas License No. L03549 and a copy of the operating and emergency procedures were not available at the time of inspection. Robco Production Logging, Inc. now has a copy of the Texas License and a copy of the operating and emergency procedures on each truck and will be there permanently.

B. 10 CFR 71.5(a); 49 CFR 172.200(a): a copy of the appropriate shipping papers for the hazardous material transported was not available. Robco Production Logging, Inc. has as of today, 1-28-91, a copy of the shipping papers describing the hazardous material on the truck for inspection at all times.

49 CFR 172.310: transport container was not labeled as required. Robco Production Logging, Inc. has had new transport containers constructed to conform to the DOT requirements of transporting Type "A" materials. These containers have been durably marked with lettering one inch high with the words "TYPE A".

9102140210 910128
PDR STPRG ESGTX
PDR

140015

P.O. BOX 1423 / SNYDER, TEXAS 79549 / (915) 573-8531

IE07

91-332

~~IE07~~

These steps have been taken and completed this day
January 28, 1991 in order to be in full compliance
with all NRC regulations.

Thank you for you cooperation and consideration.



William Howard Robinson
President and Radiation Safety Officer
Robco Production Logging, Inc.