

APPENDIX

U.S. NUCLEAR REGULATORY COMMISSION
REGION IV

NRC Inspection Report: 50-445/91-04
50-446/91-04

Operating License: NPF-87
Construction Permit: CPPR-127

Dockets: 50-445
50-446


Licensee: TU Electric (TUEC)
Skyway Tower
400 North Olive Street, L.B. 81
Dallas, Texas 75201

Facility Name: Comanche Peak Steam Electric Station (CPSES)


Inspection At: CPSES, Glen Rose, Texas

Inspection Conducted: January 23-24, 1991


Inspectors:


A. B. Earnest, Physical Security Specialist
Nuclear Materials and Safeguards Inspection
Section

2/5/91
Date



R. A. Caldwell, Physical Security Specialist
Nuclear Materials and Safeguards Inspection
Section

2/5/91
Date


R. A. Caldwell, Radiation Specialist, Nuclear
Materials and Safeguards Inspection Section

2/5/91
Date

Approved:


Charles L. Cain, Chief, Nuclear Materials and
Safeguards Inspection Section

2/6/91
Date

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED

Inspection Summary

Inspection Conducted January 23-24, 1991 (Report 50-445/91-04)

Areas Inspected: Routine, announced inspection of the licensee's physical security program.

The scope of the inspection was limited to recent changes and additions to the licensee security structures, systems, and program. The inspectors observed the operation of the recently activated materials inspection warehouse (MIW) and received a briefing and tour of the radiation control area access point under construction.

In addition, the inspectors observed licensee testing of the changes in the protected area (PA) detection aids system, assessment aids system, personnel access control equipment, and package access control equipment made as a result of the changes and additions to the alternate access point (AAP) and the MIW.

Results: Within the areas inspected, no violations or deviations were identified. The program appears to be well managed and receives the support of licensee management.

The licensee's management staff has demonstrated competent and proficient security program initiatives that enhance the security program. The licensee's interdepartmental cooperation and coordination appears excellent in achieving security program requirements and efficiencies of operations.

Inspection Conducted January 23-24, 1991 (Report 50-446/91-04)

No inspection of Unit 2 activities was conducted.

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED