MATERIAL TRANSMISSION HEDEWITH FUNTAINS 2.790 IN OKMALION

Docket Number 70-53

Department of United States Army U. S. Army Calibration and Repair Center Sacramento Army Depot Sacramento, California 95813

Attention: Colonel John Miller Depot Commander

Gentlemen:

This letter refers to a routine Safeguards inspection of your activities authorized by NRC License Number SNM-507 by Mr. A. Wieder of this office on March 2 and 3, 1983.

The inspection specifically pertained to your program for periodically filing Special Nuclear Material Balance Reports in accordance with applicable requirements of Title 10, Code of Federal Regulations, Part 20, "Domestic Licensing of Special Nuclear Material."

Within the scope of this inspection, one item of noncompliance was noted.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, documentation of the findings of your control and accounting procedures for safeguarding special nuclear material are exempt from public disclosure; therefore, the enclosed inspection report will not be placed in the Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance provisions of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

MATERIAL TRANSMITTED HEREWITH CONTAINS 2.790 INFORMATION

MATERIAL TRANSMITTED HEREWITH CONTAINS 2.790 INFORMATION

Department of U. S. Army

-2-

MAR 1 0 1983

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

Original signed by

LeRoy R. Norderhaug, Chief Safeguards Branch

Enclosure: Inspection Report No. 70-53/83-01 (IE-V-555)

bcc: R3B/Document Control Desk (RIDS)

Distributed by RV: State of CA (w/o enc) RHE (w/o enc) A. Johnson (w/o enc)

MATERIAL TRANSMITTED HEREWITH CONTAINS
2.790 INFORMATION