

POWER AUTHORITY OF THE STATE OF NEW YORK

10 COLUMBUS CIRCLE NEW YORK, N. Y. 10019

(212) 397-6200

TRUSTEES

JOHN S. DYSON  
CHAIRMAN  
GEORGE L. INGALLS  
VICE CHAIRMAN  
RICHARD M. FLYNN  
ROBERT I. MILLONZI  
JAMES L. LAROCCA



February 28, 1983  
JPN-83-17

LEROY W. SINCLAIR  
PRESIDENT & CHIEF  
OPERATING OFFICER  
WALTER T. KICINSKI  
FIRST EXECUTIVE  
VICE PRESIDENT &  
CHIEF ADMINISTRATIVE  
OFFICER  
JOSEPH R. SCHMIEDER  
EXECUTIVE VICE  
PRESIDENT & CHIEF  
ENGINEER  
STEPHEN L. BAUM  
SENIOR VICE PRESIDENT  
& GENERAL COUNSEL

United States Nuclear Regulatory Commission  
Region I  
631 Park Avenue  
King of Prussia, PA 19406

Attention: Mr. Ronald C. Haynes  
Regional Administrator


Subject: James A. FitzPatrick Nuclear Power Plant  
Docket No. 50-333  
Response to IE Bulletin No. 82-04

Reference: NRC IE Bulletin No. 82-04, "Deficiencies in  
Primary Containment Electrical Penetration  
Assemblies," dated December 3, 1982.


Dear Sir:

The Power Authority has reviewed the subject IE Bulletin and has determined that Bunker Ramo electrical penetration assemblies which use the hard epoxy module design are not installed or planned to be installed in safety-related systems at the plant.

Very truly yours,

  
J. P. Bayne  
Executive Vice President  
Nuclear Generation

State of New York  
County of Westchester  
Subscribed and Sworn to before me  
this 14 Day of March 1983

  
Notary Public

8303160206 830228  
PDR ADOCK 05000333  
Q PDR

IEH

Attachment to JPN-83-17 , February 28, 1983  
James A. FitzPatrick Nuclear Power Plant

cc: Mr. J. Linville  
Resident Inspector  
U. S. Nuclear Regulatory Commission  
P. O. Box 136  
Lycoming, NY 13093

Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555