CONTROL BLOCK:		IPLEASE PRINT OR TYPE ALI	REQUIRED INFORMATION
A L J M I	F 2 2 0 0 - 0 0 0 CICENSE	0 0 0 1 - 10 10 3 4 11	LICENSE TYPE 30 4 57 CAT 58 5
	O O O O O O O O O O O O O O O O O O O		B 1 2 0 2 8 1 9
2 At 1700 on 1	1/3/81, while performing	FNP-2-STP-28.2 (DC 2B ope	erability test) diesel
[]3 generator 2B	was declared inoperable	when the B2G sequencer fa	ailed to meet the time
14 requirements	for picking up step 5.	(Note: DG 1-2A was out of	service for maintenance).
Tech. Spec.	3.8.1.1, in part, require	s DG 2B to be operable.	Tech. Spec. 3.8.1.1.e
16 action state	ment requirements were me	t. Health/Safety of the	public was not affected.
117			
18			80
	TEM CAUSE CAUSE SUBCODE E 11 E 12 A 13	RELAYX	OMP. SUBCODE M 15 Z 16
17 REPORT LE	TYEAR SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REFORT REVISION TYPE NO:
ACTION FUTURE TAKEN ACTION E 18 Z 19 CAUSE DESCRIPTIO	EFFECT SHUTDOWN METHOD IN PLANT METHOD IN SHORT IN AND CORRECTIVE ACTIONS (27)	HOURS (22) ATTACHMENT SUBMITTED FORM SU	
	as caused by setpoint dri	ft of the agastat timer.	The timer was adjusted
and followin	g the successful completi	on of FNP-2-STP-28.2, DG	2B was returned to
]]2] [service at 1	715 on 11/3/81.		
113			
14			90
FACILITY STATUS STATUS	OTHER STATUS 30 NA NA 44	B 31 Surveillance	Test 80
ACTIVITY CONTENT RELEASED OF RELEASE 1 6 Z 33 Z 34	AMOUNT OF ACTIVITY (35)	NA NA	ATION OF RELEASE (36)
PERSONNEL EXPOS	Z 38 NA		80
NUMBER DI 40L	ESCR PTION(41)		
LOSS OF OR DAMAGE T	O FACILITY (43)		80
1 9 Z 42 L	NA NA		80
PUBLICITY ISSUED DESCRIPTION	NA NA		NRC USE ONLY
8112240139 PDR ADOCK 050			68 69 80 5
S ADUCK 050	W. G. Hairston	, III PHON	(205) 899-5156