

33 MAR 11

P.S

COFFICIAL COPY !

IE27

Carolina Power & Light Company

P. O. Box 101, New Hill, North Carolina March 4, 1983

FILE: SH N-2/18 Item 108

Mr. James P. O'Reilly United States Nuclear Regulatory Commission Region II 101 Marietta Street, Northwest Atlanta, Georgia 30303

> SHEARON HARRIS NUCLEAR POWER PLANT, UNITS 1 AND 2 DOCKET NOS. 50-400, 50-401 REACTOR COOLANT PUMP MOTOR FRAME WELD DEFICIENCIES

Dear Mr. O'Reilly:

This letter is to confirm the March 4, 1983 telephone conversation between Mr. N. J. Chiangi and Mr. A. Hardin. Mr. A. Hardin was informed that the December 2, 1982 potentially reportable item, pertaining to welding deficiencies in the Reactor Coolant Pump Motor Frame received from Westinghouse, has been evaluated and considered not to be reportable per the provisions of 10CFR50.55(e) and 10CFR, Part 21.

Thank you for your consideration in this matter.

Yours very truly,

n.J. Cuingi

N. J. Chiangi - Manager Quality Assurance/Quality Control Harrıs Plant

NJC/mt

cc: Mr. G. Maxwell Mr. V. Stello