February 17, 1983

In reply, please refer to LAC-8883

DOCKET NO. 50-409

Mr. James G. Keppler Regional Administrator Directorate of Regulatory Operations U. S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

SUBJECT: DAIRYLAND POWER COOPERATIVE

LA CROSSE BOILING WATER REACTOR (LACHWR) PROVISIONAL OPERATING LICENSE NO. DPR-45 ANNUAL REPORT FOR 1982 - REPORT OF CHANGES.

TESTS AND EXPERIMENTS FOR 1982

References:

(1) LACBUR Technical Specifications, Section 6.9.1.5

(2) 10 CFR 50.59(b)

(3) NUREG-0737, dated October 31, 1980, Section II.K.3.(3)

Jear Mr. Keppler:

In accordance with Reference (1), we are submitting the Annual Report for 1982 covering the radiological exposure summary.

Also included are brief descriptions of changes and tests, including summaries of the safety evaluations of each required by the provisions of Reference (2). No experiments were conducted during this reporting period.

In accordance with Reference (3), this report also includes the annual report of safety valve failures. There were no safety valve failures during 1982.

If there are any questions concerning this report, please contact us.

Very truly yours,

DAIRYLAND POWER COOPERATIVE

James Deugler Frank Linder, General Manager

FL:LSG:dh Enclosures

cc - NRC Resident Inspector Document Control Desk, USNRC, Wash.

WP6.7

IE25