

May 23, 1994

Docket Nos. 50-348
and 50-364

Mr. D. N. Morey, Vice President
Southern Nuclear Operating Co., Inc.
Post Office Box 1295
Birmingham, Alabama 35201-1295

Dear Mr. Morey:

SUBJECT: RESPONSE TO NRC BULLETIN 93-02, "DEBRIS PLUGGING OF EMERGENCY CORE COOLING SUCTION STRAINERS" - JOSEPH M. FARLEY NUCLEAR PLANT, UNITS 1 AND 2 (TAC NOS. M86560 AND M86561)

This letter acknowledges receipt of your response dated June 8, 1993, to NRC Bulletin 93-02 (Bulletin). The Bulletin was issued May 11, 1993, to all nuclear power reactor licensees. It requested licensees to identify fibrous material in the primary containment, to take any necessary compensatory measures, and to remove any such material. Your response stated that no sources of fibrous filter material like that described in the Bulletin was identified as being used and/or stored inside your containment during operating modes 1 through 4. Your response further stated that any fibrous materials used or temporarily stored in containment during modes 5 and 6 are verified to be removed by procedure prior to startup. Based on the information provided, we consider your actions to be complete. As subsequent inspection activities may be conducted with regard to this issue, please retain any records of your actions in response to this Bulletin.

Should you have any questions, please contact me at (301) 504-1463 or the lead Project Manager for this issue, John B. Hickman, at (301) 504-3017.

Sincerely,

Original Signed by:
Byron L. Siegel, Project Manager
Project Directorate
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation

cc: see next page

DISTRIBUTION:

Docket File	S. Varga	P. Anderson	ACRS
NRC & Local PDRs	G. Lainas	B. Siegel	E. Merschoff, RII
PDII-1 R/F	W. Bateman	OGC	J. Hickman
			R. Barrett

OFC	LA:PDII-1	PM:PDII-1	D:PDII-1		
NAME	PAnderson	BSiegel	WBateman		
DATE	5/20/94	5/20/94	5/20/94		

OFFICIAL RECORD COPY
DOCUMENT NAME: G:\FARLEY\FAB6560.LTR

9405310088 940523
PDR ADOCK 05000348
G PDR

260061

NRC FILE CENTER COPY

DFU 1/0



UNITED STATES
NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

Docket Nos. 50-348
and 50-364

May 23, 1994

Mr. D. N. Morey, Vice President
Southern Nuclear Operating Co., Inc.
Post Office Box 1295
Birmingham, Alabama 35201-1295

Dear Mr. Morey:

SUBJECT: RESPONSE TO NRC BULLETIN 93-02, "DEBRIS PLUGGING OF EMERGENCY CORE COOLING SUCTION STRAINERS" - JOSEPH M. FARLEY NUCLEAR PLANT, UNITS 1 AND 2 (TAC NOS. M86560 AND M86561)

This letter acknowledges receipt of your response dated June 8, 1993, to NRC Bulletin 93-02 (Bulletin). The Bulletin was issued May 11, 1993, to all nuclear power reactor licensees. It requested licensees to identify fibrous material in the primary containment, to take any necessary compensatory measures, and to remove any such material. Your response stated that no sources of fibrous filter material like that described in the Bulletin was identified as being used and/or stored inside your containment during operating modes 1 through 4. Your response further stated that any fibrous materials used or temporarily stored in containment during modes 5 and 6 are verified to be removed by procedure prior to startup. Based on the information provided, we consider your actions to be complete. As subsequent inspection activities may be conducted with regard to this issue, please retain any records of your actions in response to this Bulletin.

Should you have any questions, please contact me at (301) 504-1463 or the lead Project Manager for this issue, John B. Hickman, at (301) 504-3017.

Sincerely,

A handwritten signature in cursive script that reads "Byron L. Siegel".

Byron L. Siegel, Project Manager
Project Directorate
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation

cc: see next page

Mr. D. N. Morey
Southern Nuclear Operating
Company, Inc.

Joseph M. Farley Nuclear Plant

cc:

Mr. R. D. Hill, Jr.
General Manager - Farley Nuclear Plant
Southern Nuclear Operating Company
Post Office Box 470
Ashford, Alabama 36312

State Health Officer
Alabama Department of Public Health
434 Monroe Street
Montgomery, Alabama 36130-1701

Mr. B. L. Moore, Licensing Manager
Southern Nuclear Operating Company
Post Office Box 1295
Birmingham, Alabama 35201-1295

Chairman
Houston County Commission
Post Office Box 6406
Dothan, Alabama 36302

James H. Miller, III, Vice President
and Corporate Counsel
Southern Nuclear Operating Company
Post Office Box 1295
Birmingham, Alabama 35201

Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta St., N.W., Ste. 2900
Atlanta, Georgia 30323

Mr. J. D. Woodard
Executive Vice President
Southern Nuclear Operating Company
P.O. Box 1295
Birmingham, Alabama 35201

Resident Inspector
U.S. Nuclear Regulatory Commission
7388 N. State Highway 95
Columbia, Alabama 36319