



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION IV  
611 RYAN PLAZA DRIVE, SUITE 400  
ARLINGTON, TEXAS 76011-8064

MAY 26 1994

Dockets: 50-445  
50-446  
Licenses: NPF-87  
NPF-89

TU Electric  
ATTN: W. J. Cahill, Jr., Group Vice President  
Nuclear Engineering and Operations  
Skyway Tower  
400 North Olive Street, L.B. 81  
Dallas, Texas 75201

SUBJECT: NRC INSPECTION REPORT 50-445/94-12; 50-446/94-12 (NOTICE OF VIOLATION)

This refers to the inspection conducted by Mr. L. T. Ricketson of this office on May 2-6, 1994. The inspection included a review of activities authorized for your Comanche Peak Steam Electric Station, Units 1 and 2, facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress. The purpose of the inspection was to determine whether activities authorized by the license were conducted safely and in accordance with NRC requirements.

Based on the results of this inspection, certain licensed activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). The violation is of concern because it indicates a need for stronger measures to ensure that workers comply with the requirements of the radiation work permit.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

9406010116 940526  
PDR ADOCK 05000445  
G PDR

JED6


TU Electric

-2-

The responses directed by this letter and the enclosed Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96.511.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

  
Samuel J. Collins, Director  
Division of Radiation Safety  
and Safeguards

Enclosures:

1. Appendix A - Notice of Violation
2. Appendix B - NRC Inspection Report  
50-445/94-12; 50-446/94-12

cc w/enclosures:

TU Electric

ATTN: Roger D. Walker, Manager of  
Regulatory Affairs for Nuclear  
Engineering Organization

Skyway Tower

400 North Olive Street, L.B. 81  
Dallas, Texas 75201

Juanita Ellis

President - CASE

1426 South Polk Street  
Dallas, Texas 75224

GDS Associates, Inc.

Suite 720

1850 Parkway Place  
Marietta, Georgia 30067-8237

TU Electric

Bethesda Licensing

3 Metro Center, Suite 610  
Bethesda, Maryland 20814

Jorden, Schulte, and Burchette

ATTN: William A. Burchette, Esq.

Counsel for Tex-La Electric

Cooperative of Texas

1025 Thomas Jefferson St., N.W.  
Washington, D.C. 20007

TU Electric

-3-

Newman & Holtzinger, P.C.  
ATTN: Jack R. Newman, Esq.  
1615 L. Street, N.W.  
Suite 1000  
Washington, D.C. 20036

Texas Department of Licensing & Regulation  
ATTN: G. R. Bynog, Program Manager/  
Chief Inspector  
Boiler Division  
P.O. Box 12157, Capitol Station  
Austin, Texas 78711

Honorable Dale McPherson  
County Judge  
P.O. Box 851  
Glen Rose, Texas 76043

Texas Radiation Control Program Director  
1100 West 49th Street  
Austin, Texas 78756

TU Electric

-4-

E-Mail report to D. Sullivan (DJS)

bcc to DMB (IE06)

bcc distrib. by RIV:

L. J. Callan  
Branch Chief (DRP/B)  
MIS System  
RIV File  
Branch Chief (DRP/TSS)  
L. T. Ricketson, DRSS/FIPB

Resident Inspector (2)  
Leah Tremper, OC/LFDCB, MS: MNBB 4503  
DRSS-FIPB  
Project Engineer (DRP/B)  
J. M. Reese, WCFO (DRSS/FIPB)

RIV:FIPB <i>See</i>	C:FIPB <i>See</i>	DD:DRSS <i>See</i>	D:DRP <i>See</i>	D:DRSS
LTRicketson:cd	JHReese		ABBeach	SJCollins
5/25/94	5/25/94	5/25/94	5/26/94	5/26/94

TU Electric

-4-

E-Mail report to D. Sullivan (DJS)

~~bcc to DMB (IE06)~~

bcc distrib. by RIV:

L. J. Callan  
Branch Chief (DRP/B)  
MIS System  
RIV File  
Branch Chief (DRP/TSS)  
L. T. Ricketson, DRSS/FIPB

Resident Inspector (2)  
Leah Tremper, OC/LFDCB, MS: MNBB 4503  
DRSS-FIPB  
Project Engineer (DRP/B)  
J. M. Reese, WCFO (DRSS/FIPB)

RIV:FIPB <i>See</i>	C:FIPB <i>See</i>	DD:DRSS <i>See</i>	D:DRP <i>See</i>	D:DRSS
LTRicketson:cd	JHReese		ABBeach	SJCollins
5/25/94	5/25/94	5/25/94	5/24/94	5/24/94