

March 8, 1983

Log No. K83-432 File: RR2 (NP 33-83-12)

Docket No. 50-346 License No. NPF-3

Mr. James G. Keppler Regional Administrator, Region III Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

LER No. 83-009 Davis-Besse Nuclear Power Station Unit 1 Date of Occurrence: February 7, 1983

Enclosed are three copies of Licensee Event Report 83-009 which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D Murray

Terry D. Murray Station Superintendent Davis-Besse Nuclear Power Station


TDM/1jk

Enclosures

cc: Mr. Richard DeYoung, Director Office of Inspection and Enforcement Encl: 30 copies

> Mr. Norman Haller, Director Office of Management and Program Analysis Encl: 3 copies

Mr. Tom Peebles NRC Resident Inspector Encl: 1 copy



IEZZ

EDISON PLAZA 300 MADISON AVENUE

TOLEDO, OHIO 43652