NRC FORM 591 PART 1 (7-91) 10 CFR 2.201	SAFETY	INSPECTION	U.S. NUCLEAR REGL	Page 1 of _2
1. LICENSEE Hawaii Geotechnical Group, Inc. 98-722 Kuahao Place Pearl City, Hawaii 96782		2. REGIONAL OFFICE REGION ^{IV} U S NUCLEAR REGULATORY COMMISSION 1450 MARIA LANE SUITE 210 WALNUT CREEK CA 94596-5368		
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE OF INSPECTION	
030-20451	53-23280-01		April 18, 1994	
 Within the scope of this inspection. The inspector also verified the step: questions on those actions at this till During this inspection certain of you NOTICE OF VIOLATION, which is reliable indicate the presence of a	s you have taken to corre me. ur activities, as described iquired to be posted in a uencies. 10 CFR	ict the violations identified below or attached, were ccordance with 10 CFR 19	n violation of NRC requirement 11. was not properly 10 CFR 20.203 of sealed source Condition Number	ts. This form is a posted to s(b),(c),(d),(e) or 34.42. is were not
D. Documents were not propert				
E. Reports or notification of	or License Condition	Number		in accordance with
I hereby state that, within 30 days, the action above. This statement of corrective actions i unless required by the NRC.				
SIGNATURE - LICENSEE	DATE	SIGNATURE - NRC IN James J. M	SPECTOR bordgomeny	DATE 5/23/94