

APPENDIX A

Alloy Rods, Incorporated  
Docket No. 99900806/83-01

NOTICE OF VIOLATION

As a result of the inspection conducted on January 24-28, 1983, and in accordance with Section 206 of the Energy Reorganization Act of 1974 and its implementing regulation 10 CFR Part 21, the following violation was identified and has been categorized in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), 47 FR 9987 (March 9, 1982):

Section 21.6 of 10 CFR Part 21, dated September 1, 1982, states, in part, "(a) Each . . . corporation . . . subject to the regulations in this part, shall post current copies of the following documents . . . (1) the regulations in this part, (2) Section 206 of the Energy Reorganization Act of 1974 . . . ."

Contrary to the above:

1. A copy of 10 CFR Part 21 that was posted was not the current copy dated September 1, 1982.
2. A copy of Section 206 was not posted.

This is a Severity Level V Violation (Supplement VII).