

Public Service Electric and Gas Company P.O. Box E Hancocks Bridge, New Jersey 08038

Salem Generating Station

March 11, 1983

Mr. R. C. Haynes Regional Administrator USNRC Region 1 631 Park Avenue King of Prussia, Pennsylvania 19406

Dear Mr. Haynes:

LICENSE NC. DPR-70 DOCKET NO. 50-272 REPORTABLE OCCURRENCE 83-011/01T

Pursuant to the requirements of Salem Generating Station Unit No. 1 Technical Specifications, Section 6.9.1.8.c, we are submitting Licensee Event Report for Reportable Occurrence 83-011/01T. This report is required within fourteen (14) days of the occurrence.


Sincerely yours,

1.12 spicture

H. J. Midura General Manager -Salem Operations

RF:ks

CC: Distribution



IE22

Report Number:	83-011/01T	
Report Date:	03-10-83	
Occurrence Date:	02-25-83	
Facility:	Salem Generating Station Unit 1 Public Service Electric & Gas Company Hancock's Bridge, New Jersey 08038	

IDENTIFICATION OF OCCURRENCE:

Reactor Trip System - Reactor Trip Breakers - Inoperable.

This report was initiated by Incident Report 83-034.

CONDITIONS PRIOR TO OCCURRENCE:

Mode 1 - RX Power 12 % - Unit Load 70 MWe.

DESCRIPTION OF OCCURRENCE:

On February 25, 1983, during a routine startup of Salem Unit 1, both reactor trip breakers failed to open automatically on receipt of a valid Low-Low Steam Generator Level reactor trip signal. The reactor was shutdown 25 seconds later using the manual trip on the control console. Following the trip, the plant was placed in a stable shutdown condition. A plant cooldown was subsequently performed, and the unit entered Mode 5 at 0254 hours, February 26, 1983.

Letters to the NRC dated March 1 and 8, 1983, provide documentation of the investigation of the incident and proposed corrective action. A Supplemental Report will be submitted documenting the occurrence in detail.

FAILURE DATA:

Westinghcuse Electric Corp. Air Circuit Breaker Model DB-50 Type A

Prepared By R. Frahm

relichura

General Manager -Salem Operations

SORC Meeting No. 83-031B