

CONTROL BLOCK: [] [] [] [] [] [] [] [] [] [] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[01] N C M G S I [2] 0 0 - 0 0 0 0 0 0 - 0 0 [3] 4 1 1 1 1 [4] [] [5]

CONT
[01] REPORT SOURCE [L] [5] 0 5 0 0 0 3 6 9 [7] 0 8 1 2 8 2 [8] 0 9 1 0 8 2 [9]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
[02] While in mode 1, when a ventilation unit condensate drain tank (VUCDT) release
[03] to the condenser circulating water system (RC) was commenced (on 8/12/82) the
[04] VUCDT flow totalizer did not count and was therefore declared inoperable per
[05] T.S.3.3.3.8. After termination of another VUCDT to RC release (on 8/20/82), the
[06] totalizer continued to count slowly for approximately 5 minutes and was again
[07] declared inoperable. These are reportable per T.S.6.9.1.13(b). Since alter-
[08] nate methods of determining flow are available, health and safety of the public
[09] were unaffected.

[09] SYSTEM CODE [M] [C] [11] CAUSE CODE [X] [12] CAUSE SUBCODE [Z] [13] COMPONENT CODE [I] [N] [S] [T] [R] [U] [14] COMP. SUBCODE [Q] [15] VALVE SUBCODE [Z] [16]
[17] LER/RO REPORT NUMBER [8] [2] [18] SEQUENTIAL REPORT NO. [0] [6] [6] [19] OCCURRENCE CODE [0] [3] [20] REPORT TYPE [L] [21] REVISION NO. [0]
[22] ACTION TAKEN [X] [18] FUTURE ACTION [X] [19] EFFECT ON PLANT [Z] [20] SHUTDOWN METHOD [Z] [21] HOURS [0] [0] [0] [0] [22] ATTACHMENT SUBMITTED [Y] [23] NPRO-4 FORM SUB [N] [24] PRIME COMP. SUPPLIER [L] [25] COMPONENT MANUFACTURER [X] [9] [9] [9] [26]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
[10] The cause for the failures appears to be occasional unusual process conditions
[11] under which the totalizer cannot function properly, however, the cause of these
[12] conditions is not known at present. After both failures pump head curves were
[13] used to determine flow as allowed by T.S. action statements. A long term solution
[14] to identify and rectify the cause is being pursued, with a followup report to be
[15] submitted.

[15] FACILITY STATUS [B] [28] % POWER [0] [5] [0] [29] OTHER STATUS [8/20/82=075%] [30] METHOD OF DISCOVERY [B] [31] DISCOVERY DESCRIPTION [Routine Surveillance] [32]
[16] ACTIVITY RELEASED [Z] [33] CONTENT OF RELEASE [Z] [34] AMOUNT OF ACTIVITY [N/A] [35] LOCATION OF RELEASE [N/A] [36]

[17] PERSONNEL EXPOSURES NUMBER [0] [0] [0] [37] TYPE [Z] [38] DESCRIPTION [N/A] [39]

[18] PERSONNEL INJURIES NUMBER [0] [0] [0] [40] DESCRIPTION [N/A] [41]

[19] LOSS OF OR DAMAGE TO FACILITY TYPE [Z] [42] DESCRIPTION [N/A] [43]

[20] PUBLICITY ISSUED [N] [44] DESCRIPTION [N/A] [45]

NAME OF PREPARER Phillip B. Nardoci PHONE: (704)373-7432

8209210329