

OFFICIAL RECORD COPY

MAY 18 1994

Docket No. 150-00003
License No. ARK-796-BP-AS-98

Graseby STI
ATTN: Michael A. Halter
P. O. Box 2470
45 Fir Street
Waldron, Arkansas 72958-2470

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. ARK-796-BP-AS-98/94-01

Thank you for your response of May 4, 1994, to our Notice of Violation, issued on April 19, 1994, concerning activities conducted under reciprocity at the Cogentrix facility in Richmond, Virginia. We have evaluated your response and found that it meets the requirements of 10 CFR 2.201. We will examine the implementation of your corrective actions during future inspections.

We appreciate your cooperation in this matter.

Sincerely,

ORIGINAL SIGNED BY
DAVID R. McGUIRE

Douglas M. Collins, Chief
Nuclear Materials Safety and
Safeguards Branch
Division of Radiation Safety
and Safeguards

cc: Commonwealth of Virginia

bcc: Document Control Desk
RII Docket File, DRSS

SEND	OFC	RII:DRSS	RII:DRSS			
TO	NAME	JMumper <i>JMumper</i>	CHosey <i>CHosey</i>			
PDR?	DATE	05/17/94	05/18/94	/ /94	/ /94	/ /94
<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> COPY? Yes	<input type="radio"/> No	<input type="radio"/> Yes	<input checked="" type="radio"/> No	<input type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Yes <input type="radio"/> No

OFFICIAL RECORD COPY

DOCUMENT NAME: G:\drss\nmis\graseby.ack

030005
9406060071 940518
PDR STPRG ESCAR
PDR

IEO9

Mumper

GRASEBY
STI

May 4, 1994

Regional Administrator
United States
Nuclear Regulatory Commission
Region II
101 Marietta Street, N.W.
Atlanta, GA 30323


REPLY TO A NOTICE OF VIOLATION

This correspondence is in response to a Notice of Violation dated April 19, 1994, Docket No. 150-00003. As discussed with the inspector, Mr. J. Mumper on March 29, 1994 during a telephone conversation, the Model 4000 ammonia analyzer is secured in a locked cabinet which at the time of inspection was unlocked for display by a testing company which was on site. The cabinet was to be secured at the end of the work day by a Cogentrix employee and was to remain locked until the return of the licensee.

Since the time of inspection, the cabinet has remained secured except under the direct supervision of the licensee. A key to the access doors of the cabinet has been left in the possession of Mr. Gene McGhan at the Cogentrix facilities for reasons of safety. A voltage output from the Model 4000 has been provided to the Cogentrix control room to eliminate the need for access to the cabinet.

Should you have any further questions, please contact us.

Sincerely,



Michael Halter, RSO
Director, Research and Development

cc: USNRC Document Control Desk

9405160142