

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION
P.O. BOX 128
SAN CLEMENTE, CALIFORNIA 92672

March 3, 1983

H. B. RAY
STATION MANAGER

RECEIVED
NRC
1983 MAR -7 PM 1:50
SCE
REGION V
TELEPHONE
(714) 492-7700

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator

Subject: Docket No. 50-362
30-Day Report
Licensee Event Report No. 83-001, Revision 1
San Onofre Nuclear Generating Station, Unit 3

Reference: Letter, H.B. Ray (SCE) to R.H. Engelken (NRC),
dated February 10, 1983.

The enclosed Licensee Event Report (LER) for an occurrence involving Limiting Condition for Operation (LCO) 3.6.3 associated with Containment Isolation Valves has been revised to correct Licensee Code and Docket Number which were in error on Revision 0 of the subject LER.

If there are any questions regarding the above, please contact me.

Sincerely,

HBRay / M (M) M

cc: A. E. Chaffee (USNRC Resident Inspector, San Onofre Units 2 & 3)
R. Pate (USNRC Resident Inspector, San Onofre Units 2 & 3)

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U. S. Nuclear Regulatory Commission
Office of Management Information and Program Control

Institute of Nuclear Power Operations

8303180435 830303
PDR ADDCK 05000362
S PDR

IE-22
83-99