

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION
P.O. BOX 128
SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY
STATION MANAGER

March 3, 1983

RECEIVED
MHC
SCE
1983 MAR -7 PM 1:50
REGION V
TELEPHONE
(714) 492-7700

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator

Dear Sir:

Subject: Docket Nos. 50-361 and 50-362
14-Day Follow-Up Report
Licensee Event Report No. 83-018
San Onofre Nuclear Generating Station, Units 2 and 3

Pursuant to Section 6.9.1.12.b and .i of Appendix A, Technical Specifications to Facility Operating Licenses NPF-10 and NPF-15 for San Onofre, Units 2 and 3, respectively, this submittal provides the required 14-day follow-up written report and a copy of the Licensee Event Report (LER) for an occurrence involving Limiting Condition for Operation (LCO) 3.3.3.9 associated with radiation monitoring instrumentation. Enclosed LER 83-018 addresses this event, including corrective actions and measures to prevent recurrence.

If there are any questions regarding this event, please contact me.

Sincerely,

HBRay / RHM

Enclosure: LER 83-018 (Unit 2)

cc: A.E. Chaffee (USNRC Resident Inspector, San Onofre, Units 2 and 3)
R.J. Pate (USNRC Resident Inspector, San Onofre, Units 2 and 3)

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission
Office of Management Information and Program Control

Institute of Nuclear Power Operations (INPO)

8303180481 830303
PDR ADOCK 05000361
S PDR

IE-22
83-100