



SAFEGUARDS INFORMATION

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA STREET, N.W., SUITE 2900
ATLANTA, GEORGIA 30323-0199

Report Nos. 50-259/94-08, 50-260/94-08, and 50-296/94-08

Licensee: Tennessee Valley Authority
6N 38A Lookout Place
1101 Market Street
Chattanooga, TN 37402-2801

Docket Nos. 50-259, 50-260
and 50-296

License Nos. DPR-33, DPR-52,
and DPR-68

Facility Name: Browns Ferry 1, 2, and 3

Inspection Conducted: April 25 - 29, 1994

Inspector: David Thompson
D. Thompson, Safeguards Inspector

5-18-94
Date Signed

Accompanying Personnel: D. McGuire, Chief, Safeguards Section
A. Tillman, Safeguards Inspector

Approved by: D. McGuire
D. McGuire, Chief
Safeguards Section
Nuclear Materials Safety and Safeguards Branch
Division of Radiation Safety and Safeguards

5/18/94
Date Signed

SUMMARY

Scope:

This routine, unannounced inspection was conducted in the areas of Physical Security Program for Power Reactors, specifically; Access Control of Personnel and Vehicles; Alarm Stations and Communications; Assessment; and Security Training and Qualification.

Results:

In the areas inspected, a violation was identified. One violation of regulatory requirements relating to misissue of security badges was confirmed. In addition, an inspector followup item was established to track the licensee's efforts to improve the assessment capabilities for the protected area perimeter. Review and observation of routine security operational activities confirmed that the security force was performing at an acceptable level. However, the continuing degradation in security systems and equipment, all of which is programmed for replacement as part of the security upgrade, was demonstrated by the unexplained failure of the printing function of the security computer system on April 27, 1994.

SAFEGUARDS INFORMATION

9406060337 940518
PDR ADDC 05000259
PDR

Document transmitted herewith
contains sensitive unclassified
information. When separated from
enclosures, this document is decontrolled.