10 CFR 2.201	SAFETY INSPECTIO	Page 1 of _/_	
Bending to Vermont	2. REGIONAL OFFICE REGIONAL OFFICE U.S. 475 KIN	EGION I NUCLEAR REGULATORY COMMISSION ALLENDALE ROAD G OF PRUSSIA PA 19406-1415	
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE OF INSPECTION	
030-72708	14-28243-01	May 24, 1994	
Regulatory Commission (NRC) rules and reg	ulations and the conditions of your license. The	ate to radiation safety and to compliance with the Nuclear inspection consisted of selective examinations of spector. The findings as a result of this inspection are as	
Within the scope of this inspection,	no violations were observed.		
The inspector also verified the step questions on those actions at this to the step of the step o		ied during the last inspection. We have no further	
	ur activities, as described below or attached, we equired to be posted in accordance with 10 CFR	re in violation of NRC requirements. This form is a 19,11.	
A		was not properly posted to	
		. 10 CFR 20.203(b),(c),(d),(e) or 34.42.	
B	of sealed sources were not		
performed at the proper fred	performed at the proper frequencies. 10 CFR or License Condition Number		
C. Records of	C. Records of were not properly maintained.		
10 CFR	10 CFR or License Condition Number		
D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.			
E. Reports or notification of	E. Reports or notification of were not made in accordance with		
10 CFR	10 CFR or License Condition Number		
F.			
Accessed to the second			
DESIGNATED C	RETURN OF REGK		
I hereby state that, within 30 days, the action above. This statement of corrective actions unless required by the NRC.	ns described by me to the inspector will be taker is made in accordance with the requirements of	n to correct the violations identified in the items checked 10 CFR 2.201. No further response will be submitted	
SIGNATURE - LICENSEE CGC1 9406070014 PDR ADDCK	940524 03032708 SIGNATURE NRC	INSPECTOR DATE 5/24/54	
FDR 1			