

Appendix

NOTICE OF VIOLATION

Durkee Foods

License No. 34-00818-03

As a result of the inspection conducted on February 28, 1983, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

License Condition No. 13 states that each chromatograph detector cell containing nickel-63 shall be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above, the Hewlett Packard Detector Cell, Model No. 19303, containing a nickel-63 source, has not been leak tested since the manufacturer's leak test on August 13, 1980.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

3/17/83
Dated

for S.R. Lasuk
D. J. Sreniawski, Chief
Materials Radiation Protection
Section 2