

RICHARD P. CROUSE

Vice President Nuclear (419) 259-5221

Docket No. 50-346 License No. NPF-3 Serial No. 921

March 14, 1983

Director of Nuclear Reactor Regulation Attention: Mr. John F. Stolz Operating Reactor Branch No. 4 Division of Operating Reactors United States Nuclear Regulatory Commission Washington, D.C. 20555

Dear Mr. Stolz:

This is in response to your letter dated February 25, 1983 (Log No. 1233) that requested Toledo Edison provide the Davis-Besse Nuclear Power Station Superintendent with training for mitigating core damage. The D-B Station Superintendent will receive this training beginning this date March 14, 1983. This class will last one week and upon completion, Toledo Edison will be in compliance with the training requirement for mitigating core damage.


Very truly yours,

Mahman

RPC:RFP:lah

cc: DB-1 NRC Resident Inspector

A001



THE TOLEDO EDISON COMPANY EDISON PLAZA 300 MADISON AVENUE TOLEDO, OHIO 43652