



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
611 RYAN PLAZA DRIVE, SUITE 1000  
ARLINGTON, TEXAS 76011

cc: Dircks  
OCA  
CAReed (FOIA)


March 26, 1982

Note to: J. Sniezek, Deputy Director, IE

From: John T. Collins, Regional Administrator, Region IV

Reference: HAYWARD TYLER PUMP INSPECTION REPORT NO. 82-03

As a follow up to our telephone conversation on Friday, March 26, I have attached two replacement pages to Inspection Report No. 82-03, which was forwarded to you on March 22. The first page is the cover page to the inspection report which Mr. Roberts has signed. This should replace the one you have which shows Mr. Barnes signing for him. The second page is a revision to the inspection report identifying the subject of spare parts as an open item to be followed up during the next inspection.

  
John T. Collins  
Regional Administrator

Attachments  
As noted