

RECEIVED
MPC

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

1983 MAR 14 AM 11:24

March 4, 1983

ANPP-23175-GHD/BSK

U. S. Nuclear Regulatory Commission
Region V
Creekside Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. D. M. Sternberg, Chief
Reactor Projects Branch 1

Subject: Deficiency Evaluation Report 83-7
A 50.55(e) Report Relating to
Drillco "Maxi-Bolt" Anchors For Safety-Related
Equipment May Be Improperly Installed Due To Use
of Defective Torque/Pressure Gauge
File: 83-019-026
D.4.33.2


Reference: Telephone Conversation between P. Narbut and
G. Duckworth February 4, 1983

Dear Sir:

The NRC was notified of the subject Deficiency Evaluation in the
referenced telephone conversation, with a determination of reportability
to be made within thirty (30) days (March 4, 1983).

The deficiency has subsequently been determined to be Not Reportable
under the requirements of 10CFR50.55(e), therefore no written report is
required. Necessary documentation of the evaluation will be maintained
in APS files.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President
Nuclear Projects Management
ANPP Project Director

EEVBJr/GHD:db

cc: See Attached Page 2

1827

U. S. Nuclear Regulatory Commission
Attention: Mr. D. M. Sternberg, Chief
Page 2

March 4, 1983
ANPP-23175-GHD/BSK

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
J. A. Roedel
D. B. Fasnacht
G. C. Andogniui
J. R. Bynum
A. C. Rogers
B. S. Kaplan
W. E. Ide
J. Vorees
P. P. Klute/D. D. Green
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
R. M. Grant
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli